


How to Adjust the Contrast of a CI064-4021 /4073 Display



1. Hold all three buttons on the IDS-UNIVERSAL-01 board down while the display powered off
2. Plug power into board, while still holding buttons down. All the three lights next to the buttons will start flashing green.
3. Release all three buttons. Your chosen display will be lit.
4. Use the left button to turn the contrast up.
Use the centre button to turn the contrast down.
(NEXT, PREV and PAUSE may be labelled differently depending on the version of board being used.)
5. Once at desired contrast setting. You can turn the display off and on again and the contrast settings will be saved.

