

400A AMP CROCODILE EARTH CLAMP



Accessories

Accessories for arc welding equipment.

Stock no.	industry designation	System	current	Ø (mm) electrodes
Electrode holder clamps				
398-2797	Vestale 2	screwed	500 A	1.6 → 6.3
398-2804	Cobra	lever action	300 A	1.6 → 4
398-2810	Vestalette	screwed	250 A	1.6 → 3.2
Earth clamp				
398-2832	Bronze with spring	with spring	300 A	-
Sash brushes and hammer				
398-2860	Wooden-handled hammer	hardened steel tip		
398-2854	4-row wooden sash brush	hardened steel		